

Permanent Structure




Mobile Home



Substandard - Extensive Rehabilitation Required
 Substandard - Significant Rehabilitation Required
 Substandard - Moderate Rehabilitation Required
 Standard

★ Targeted for 1997/1998 Rehabilitation

0 ft 2000 ft 4000 ft 6000 ft



Scale 1 : 24,000

TOWN OF DRYDEN HOUSING CONDITIONS